

Message

From: Bahr, Ryan [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=D158C8FB589541409C301B1AB55CBFB6-RBAHR]
Sent: 4/26/2017 9:38:53 PM
To: Cullen, Raymond [cullen.raymond@epa.gov]
Subject: Arcelor Mittal

Ray,

I briefed Pat on this case. He wanted to know if the facility occasionally removes oil or sheen from the surface in between the outfall point and the booms. Do you know?

Assuming there are no other violations, If the sheen is no longer visible outside the booms, he's thinking maybe we send out inspection report with an informal letter asking what actions the facility has taken/will take to ensure that the discharge is not resulting in a visible sheen.

If that sounds okay, we can share that approach with the state tomorrow – on our regularly scheduled quarterly call. That call is at 1:00 in 15 A and you're welcome to attend if available. And, you can step out once we're done.